

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AA148 **TRUMP VILLAGE SHOPPING CTR**
ESE **532 NEPTINE AVE**
1/4-1/2 **BROOKLYN, NY 11224**
0.263 mi.
1387 ft. **Site 1 of 2 in cluster AA**

NY Spills **S118637663**
N/A

Relative:
Higher

Actual:
3 ft.

SPILLS:

Name: TRUMP VILLAGE SHOPPING CTR
Address: 532 NEPTINE AVE
City,State,Zip: BROOKLYN, NY 11224
Spill Number/Closed Date: 1600421 / 2016-04-13
Facility ID: 1600421
Facility Type: ER
DER Facility ID: 479907
Site ID: 525689
DEC Region: 2
Spill Cause: Housekeeping
Spill Class: Not reported
SWIS: 2401
Spill Date: 2016-04-12
Investigator: HRAHMED
Referred To: Not reported
Reported to Dept: 2016-04-12
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Citizen
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2016-04-12
Spill Record Last Update: 2016-04-13
Spiller Name: Not reported
Spiller Company: UNKNOWN CONTRACTOR
Spiller Address: 532 NEPTINE AVE
Spiller Company: 999
Contact Name: SAMUEL MYRINARISKI
DEC Memo: "4/13/16- Ahmed - Similar complaint (Spill-1600383) came yesterday about HW Site# 224047. The contractor were doing some work related to installing electric line. Sent an email to DEC William Wu, requesting him to outreach the Sam (complainer)."

Remarks: "Caller reporting tar smell from a tar pit site that is open and is not being closed properly. Caller reported the same last night and advises he will continue to call every day further that it occurs."

All Materials:

Site ID: 525689
Operable Unit ID: 1274640
Operable Unit: 01
Material ID: 2279254
Material Code: 0018A
Material Name: tar
Case No.: Not reported
Material FA: Other
Quantity: Not reported
Units: Not reported
Recovered: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Oxygenate:

Not reported